

Bookmobile Assessment Results

Bookmobile Assessment Recommendations (\$12,000 budgeted for repairs this fiscal year)						
	Recommendation	Timeframe	Estimated Cost	Actual Cost	Date Completed	Status Update
1	Inspection of rust damage & weld points on Generator & LP Tank supports by certified welder	Within 1-2 years	\$ 500.00	\$ -		Get examined on Friday, January 24
2	Propane Tank Plumbing repair/replace	Within 1-2 years	\$ 1,000.00	\$ -		Get examined on Friday, January 24
3	Underbody-rust neutralized & new layer of rubberized undercoating applied	Within 1-2 years	\$ 1,000.00	\$ -		The bookmobile weighs 24,300 pounds. We need to stay below to maintain our Class C status. We have been notified that if we do this work, there is a chance we would exceed 25,000 pounds, it would then make the bookmobile classified in the CDL range. Also, this should have been done as a protective measure 11 years ago, so we question the value of getting this done now.
4	Chassis Steering Box Fluid Leak-Replace	Within 1 year	\$ 1,500.00	\$ -		Will try to schedule during the 12/20 winterization visit
5	Generator Exhaust Piping repair/replace	Within 1 year	\$ 1,500.00	\$ -		Looks okay for now, but will need custom fabrication on the muffler
6	Front Auxiliary Step-Replace	Immediate Need	\$ 1,200.00	\$ 1,068.38	11/22/2019	
7	Power Inverter Replacement	Immediate Need	\$5,417.89	\$ 7,252.69	12/12/2019	
		Totals	\$ 12,117.89	\$ 8,321.07		